RE: Product Problem Notification: Mount Hope Fusion Wine

Dear Customer:

We have become aware of a production issue that may result in Mount Hope Fusion oxidizing in the bottle causing bottles to leak or push out the cork. We have had limited customer reports regarding this issue. Testing of oxidized wine shows no harmful contaminants.

Mount Hope Fusion Wine is pictured to the right for your reference.

If you experience any problem with your Fusion purchase contact us at:
Phone: (717) 665-7021
Email: royalspk@parenfaire.com

We apologize for any inconvenience.

Mount Hope Estate & Winery / 2775 Lebanon Road / Manheim, PA 17545